

FAA Safety Team presents:

# **IMC Club Meeting: Mastering the Art of Instrument Navigation - WAAS the Problem?**

This month's meeting deals with emergencies above the clouds. IMC Club, through its nationwide chapters, provides organized "hangar flying" focused on building instrument flying knowledge and skills. The organization network promotes a safety culture through continued education and believes that safety and proficiency are developed through education and experience. Monthly Meetings offer an opportunity to share in-flight experiences and valuable safety tips. Through the FAA Safety Program, aviation professionals offer informative WINGS presentations. You do not have to be a rated instrument pilot to attend. Membership in the international IMC Club is encouraged but not required. For more information and to attend this event, click the link below and register TODAY.

**Directions:** The meeting will be held in the KLBE Emergency Management Building. It is located on the Corner of RT. 981 and Kilo Lane. Look for the sign on the door. If you are flying in, park at Vee Neal and call for a shuttle ride at (412) 849-2103.

For more information about the Vee Neal, visit their website at <http://www.veeneal.com>

## Event Details

**Tue, Jan 19, 2016 - 19:00 EST**  
**KLBE - Emergency Management Building**

KILO Lane

Latrobe, PA 15650



**Contact: FRANK BERESNYAK**

**(412) 849-2103**

[e170ca@gmail.com](mailto:e170ca@gmail.com)

Select #: EA0366435

Representative FRANK BERESNYAK

### **A message from the National FAASafety Team Manager**

Invite a fellow pilot to the next WINGS Safety Seminar in your area.

Sign up for the FAA's safety services at [www.FAASafety.gov](http://www.FAASafety.gov)!

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the "Contact Information" area of the meeting/event notice. Note that two weeks is usually required to arrange services.